

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>NSP2093</b> (Cont'd) BD648 3 PHIN BDX34B 3 RCA D45E3 3 GESY SPM126 3 SODI	<b>NSP4923</b> TIP29B 1 MOTA BD239B 3 RCA D44C10 3 GESY	<b>NSP5981</b> (Cont'd) DE332 3 DGE <b>NSP5982</b> 2N6491 1 MOTA BDT84 3 APX DE332 3 DGE	<b>OP500</b> (Cont'd) LRT100 3 SIEX MRD160 3 MOTA OP500SLA 3 TRWO OP500W 3 TRWO OP501 3 TRWO OP501SLC 3 TRWO SDP8405-2 3 HON SDP8505-2 3 HON SEP.8402 3 HON SP213 3 MIKG SPT120 3 FSC TIL078 3 TII XC500A 3 NSC XC500D 3 NSC	<b>OP550</b> (Cont'd) K5550 2 OTK SDP8404-1 2 HON TIL411 2 TII LPT80 3 SIEX OP550SLA 3 TRWO SEP.8406 3 HON	<b>OP602</b> (Cont'd) GS1020-2 3 GSI MRD602 3 MOTA OP642 3 TRW TIL601 3 TII
<b>NSP2100</b> TIP120 1 MOTA BD645 3 PHIN BDX33A 3 RCA D44E2 3 GESY SPM120 3 SODI	<b>NSP5190</b> 2N6121 1 MOTA BD947 3 PHIN BDT31A 3 APX DE196 3 DGE	<b>NSP5983</b> 2N6486 1 MOTA BDT81 3 APX DE331 3 DGE	<b>NSP5984</b> 2N6487 1 MOTA BDT81 3 APX DE331 3 DGE	<b>OP550SLA</b> L14Q1 1 GESY MTS461 1 GIC SDP8406-4 1 HON VTT3321 2 VAC VTT7114 2 VAC VTT7125 2 VAC MTS360 3 GIC SDP8405-1 3 HON SDP8406-2 3 HON	<b>OP603</b> TIL603 1 TII 1N5724 2 TII BPX6211 2 SIEG MRD602 2 MOTA SD2440-3 2 HON STPT63 2 STE TIL603HR 2 TII GS1020-3 3 GSI MRD603 3 MOTA OP643 3 TRW STPT1630-2 3 STE TIL602 3 TII
<b>NSP2101</b> TIP120 1 MOTA BD645 3 PHIN BDX33A 3 RCA D44E2 3 GESY SPM120 3 SODI	<b>NSP5192</b> 2N6123 1 MOTA BD951 3 PHIN BDT31B 3 APX DE196 3 DGE	<b>NSP5985</b> 2N6488 1 MOTA BDT83 3 APX DE331 3 DGE	<b>OP500SLA</b> SDP8405-3 1 HON SFH309 1 SIEX XC500A 1 NSC SDP8405-6 2 HON BPW42 3 AEGG FPT700 3 FSC K5502 3 OTK K5503 3 OTK SDP8405-2 3 HON SDP8405-4 3 HON SP213 3 MIKG XC500B 3 NSC XC500E 3 NSC	<b>OP550SLB</b> L14Q1 1 GESY MTS461 1 GIC SDP8406-4 1 HON VTT3322 2 VAC VTT7113 2 VAC VTT7121 2 VAC VTT7122 2 VAC VTT7124 2 VAC CLT4160 3 CLA MTS360 3 GIC OP550SLA 3 TRWO SDP8405-2 3 HON SDP8406-1 3 HON SDP8406-3 3 HON SDP8506-1 3 HON	<b>OP604</b> TIL604 1 TII 1N5725 2 TII BPX621V 2 SIEG CLT3170 2 CLA MRD603 2 MOTA MRD604 2 MOTA SD2440-4 2 HON STPT64 2 STE TIL604HR 2 TII GS1020-4 3 GSI LISA5604 3 GESY OP644 3 TRW STPT1630-3 3 STE STPT1630-4 3 STE TIL603 3 TII TIL608 3 TII
<b>NSP2102</b> TIP121 1 MOTA BD647 3 PHIN BDX33B 3 RCA D44E3 3 GESY SPM121 3 SODI	<b>NSP5193</b> 2N6124 1 MOTA BDT32A 3 APX DE197 3 DGE	<b>NT340</b> BD128 1 ALGG 2N5656 3 NSC BD158 3 NSC BD232 3 PHIN MJE340 3 MOTA S1202 3 TOSJ	<b>OP500SLB</b> SDP8405-2 1 HON XC500D 1 NSC SDP8405-5 2 HON K5504 3 OTK K5505 3 OTK OP500SLE 3 TRWO SFH309 3 SIEX XC500C 3 NSC	<b>OP550SLC</b> L14Q1 1 GESY MTS461 1 GIC SDP8406-3 1 HON VTT3323 2 VAC VTT7112 2 VAC VTT7123 2 VAC BPW39B 3 ALGG CLT4140 3 CLA CLT4150 3 CLA CLT4160 3 CLA MTS360 3 GIC OP550SLA 3 TRWO OP550SLB 3 TRWO SDP8405-2 3 HON SDP8406-2 3 HON	<b>OP640</b> LS600 1 TII SD2440-1 1 HON GS1020-1 3 GSI OP600 3 TRWO OP601 3 TRWO STPT60 3 STE STPT61 3 STE TIL601 3 TII
<b>NSP2103</b> TIP121 1 MOTA BD647 3 PHIN BDX33B 3 RCA D44E3 3 GESY SPM121 3 SODI	<b>NSP5194</b> 2N6125 1 MOTA BDT32A 3 APX DE197 3 DGE	<b>NTM2222A</b> BSR14 3 APX BSS79C 3 SIEG PMBT2222A 3 APX	<b>OP500SLC</b> XC500C 1 NSC SDP8405-4 2 HON K5501 3 OTK SDP8405-2 3 HON XC500A 3 NSC XC500B 3 NSC	<b>OP550SLD</b> L14Q1 1 GESY MTS461 1 GIC SDP8406-2 1 HON VTT3324 2 VAC VTT7111 2 VAC BPW39B 3 ALGG CLT4140 3 CLA CLT4150 3 CLA CLT4160 3 CLA MTS360 3 GIC OP550SLA 3 TRWO OP550SLB 3 TRWO SDP8405-2 3 HON SDP8406-3 3 HON	<b>OP641</b> SD2440-1 1 HON TIL601 1 TII GS1020-1 3 GSI LISA5601 3 GESY MRD601 3 MOTA OP601 3 TRWO STPT60 3 STE STPT61 3 STE TIL601 3 TII
<b>NSP2370</b> TIP32 1 MOTA BD132 3 PHIN BD242 3 RCA D45C5 3 GESY SP4545 3 SODI STD3509 3 SOD STD3513 3 SOD	<b>NSP5195</b> 2N6126 1 MOTA BDT32B 3 APX DE197 3 DGE	<b>NTM2222B</b> MMBT2222A 1 MOTA BSR14 3 APX BSS79C 3 SIEG PMBT2222A 3 APX	<b>OP500SLE</b> SDP8405-2 1 HON XC500D 1 NSC SDP8405-5 2 HON K5504 3 OTK K5505 3 OTK OP500SLE 3 TRWO SFH309 3 SIEX XC500C 3 NSC	<b>OP550SLE</b> VTT3325 2 VAC SDP8405-3 3 HON	<b>OP642</b> TIL602 1 TII STPT1630-1 2 STE MRD602 3 MOTA OP602 3 TRWO SD2440-2 3 HON
<b>NSP2480</b> TIP31 1 MOTA BD131 3 PHIN BD241 3 RCA D44C5 3 GESY SP44C 3 SODI	<b>NSP5974</b> TIP42 1 MOTA BD202 3 PHIN BD244 3 RCA D45VM4 3 GESY SP44H 3 SOD SODI 3 SOD	<b>NTM2907A</b> MMBT2907A 1 MOTA BSR16 3 APX BSS82C 3 SIEG	<b>OP500SLD</b> XC500C 1 NSC SDP8405-4 2 HON K5501 3 OTK SDP8405-2 3 HON XC500A 3 NSC XC500B 3 NSC	<b>OP603</b> L14Q1 1 GESY MTS461 1 GIC SDP8406-2 1 HON VTT3324 2 VAC VTT7111 2 VAC BPW39B 3 ALGG CLT4140 3 CLA CLT4150 3 CLA CLT4160 3 CLA MTS360 3 GIC OP550SLA 3 TRWO OP550SLB 3 TRWO SDP8405-2 3 HON SDP8406-2 3 HON	<b>OP643</b> TIL603 1 TII STPT1630-2 2 STE MRD603 3 MOTA OP603 3 TRW TRWO 3 HON SD2440-3 3 HON
<b>NSP2481</b> TIP31A 1 MOTA BD241A 3 RCA D44C8 3 GESY	<b>NSP5975</b> TIP42A 1 MOTA BD204 3 PHIN BD244A 3 RCA D45VM7 3 GESY STD3702 3 SOD STD3704 3 SOD STD3708 3 SOD STD3711 3 SOD STD3713 3 SOD STD3714 3 SOD STD3717 3 SOD STD3722 3 SOD STD3727 3 SOD STD3730 3 SOD STD3731 3 SOD	<b>OC701</b> BCY31A 1 PHIN	<b>OP500SLD</b> XC500D 1 NSC FPT100A 2 FSC FPT120 2 FSC SDP8405-3 2 HON BPX38-4 3 SIEX K5502 3 OTK K5503 3 OTK LPT100A 3 SIEX MRD300 3 MOTA XC500B 3 NSC XC500E 3 NSC	<b>OP604</b> L14Q1 1 GESY MTS461 1 GIC SDP8406-2 1 HON VTT3324 2 VAC VTT7111 2 VAC BPW39B 3 ALGG CLT4140 3 CLA CLT4150 3 CLA CLT4160 3 CLA MTS360 3 GIC OP550SLA 3 TRWO OP550SLB 3 TRWO SDP8405-2 3 HON SDP8406-3 3 HON	<b>OP644</b> SD2440-3 3 HON
<b>NSP2490</b> TIP32 1 MOTA BD132 3 PHIN BD242 3 RCA D45C5 3 GESY SP4545 3 SODI STD3509 3 SOD STD3513 3 SOD	<b>NSP5976</b> TIP42B 1 MOTA BD244B 3 RCA BDX78 3 PHIN D45VM10 3 GESY STD3705 3 SOD STD3718 3 SOD STD3723 3 SOD STD3728 3 SOD	<b>OP300</b> SD2410-1 1 HON OP302 3 TRWO STPD1610-1 3 STE	<b>OP500SLE</b> XC500E 1 NSC FPT131 2 FSC FPT132 2 FSC SDP8405-2 2 HON K5504 3 OTK K5505 3 OTK SFH309 3 SIEX XC500C 3 NSC XC500D 3 NSC	<b>OP605</b> LS600 1 TII SD2440-1 2 HON STPT60 2 STE GS1020-1 3 GSI OP601 3 TRWO OP640 3 TRW STPT61 3 STE TIL601 3 TII	<b>OP645</b> TIL604 1 TII STPT1630-3 2 STE LISA5604 3 GESY MRD604 3 MOTA OP604 3 TRWO SD2440-4 3 HON
<b>NSP2491</b> TIP32A 1 MOTA BD242A 3 RCA D45C8 3 GESY STD3510 3 SOD STD3514 3 SOD	<b>NSP5977</b> TIP41 1 MOTA BD201 3 PHIN BD243 3 RCA D44VM4 3 GESY SP44H 3 SODI STD5901 3 SOD	<b>OP301</b> SD2410-1 1 HON OP302 3 TRWO STPD1610-1 3 STE	<b>OP500SLE</b> XC500E 1 NSC FPT131 2 FSC FPT132 2 FSC SDP8405-2 2 HON K5504 3 OTK K5505 3 OTK SFH309 3 SIEX XC500C 3 NSC XC500D 3 NSC	<b>OP606</b> L14R1 1 GESY TPS607 1 TOSJ K9010 2 OTK CLR4180 3 CLA LPD80 3 SIEX MTS360 3 GIC	<b>OP700</b> FPT101 2 FSC
<b>NSP2520</b> TIP31 1 MOTA BD131 3 PHIN BD241 3 RCA D44C5 3 GESY SP44C 3 SODI	<b>NSP5978</b> TIP41A 1 MOTA BD203 3 PHIN BD243A 3 RCA D44VM7 3 GESY STD5902 3 SOD	<b>OP302</b> SD2410-2 1 HON STE 2 STE GS1030-1 3 GSI OP303 3 TRWO SD2410-1 3 HON STPD1610-2 3 STE	<b>OP500SLE</b> XC500E 1 NSC FPT131 2 FSC FPT132 2 FSC SDP8405-2 2 HON K5504 3 OTK K5505 3 OTK SFH309 3 SIEX XC500C 3 NSC XC500D 3 NSC	<b>OP607</b> LS600 1 TII SD2440-1 2 HON STPT60 2 STE GS1020-1 3 GSI OP601 3 TRWO OP640 3 TRW STPT61 3 STE TIL601 3 TII	<b>OP800</b> BPW14 1 ALGG BPY62-1 1 SIEX L14G2 1 GESY MRD3055 1 MOTA MTH320 1 GIC SD5443-1 1 HON TIL81 1 TII K5253 2 OTK MRD3050 2 MOTA MRD3051 2 MOTA BPX43 3 SIEG BPX43-1 3 SIEX BPY62-1 3 SIEX BPY62-2 3 SIEX CLT2130 3 CLA FPT510A 3 FSC GS4021-1 3 GSI L14G1 3 GESY L14G3 3 GESY MRD300 3 MOTA MRD310 3 MOTA MRD3052 3 MOTA MRD3053 3 MOTA MRD3054 3 MOTA MRD3055 3 MOTA MT2 3 GIC OP801 3 TRWO
<b>NSP2555</b> MJE2955T 1 MOTA PH2955T 3 APX	<b>NSP5979</b> TIP41B 1 MOTA BD244B 3 RCA BDX78 3 PHIN D45VM7 3 GESY STD3705 3 SOD STD3718 3 SOD STD3723 3 SOD STD3728 3 SOD	<b>OP303</b> SD2410-3 1 HON STPD1610-2 2 STE CLR3180 3 CLA GS1030-1 3 GSI GS1030-2 3 GSI GS1030-3 3 GSI OP305 3 TRWO SD2410-2 3 HON	<b>OP500SLE</b> XC500E 1 NSC FPT131 2 FSC FPT132 2 FSC SDP8405-2 2 HON K5504 3 OTK K5505 3 OTK SFH309 3 SIEX XC500C 3 NSC XC500D 3 NSC	<b>OP608</b> L14R1 1 GESY TPS607 1 TOSJ K9010 2 OTK CLR4180 3 CLA LPD80 3 SIEX MTS360 3 GIC	<b>OP801</b> TIL601 1 TII 1N5722 2 TII SD2440-1 2 HON STPT61 2 STE TIL601HR 2 TII GS1020-1 3 GSI LISA5601 3 GESY MRD601 3 MOTA STPT60 3 STE
<b>NSP3054</b> TIP31A 1 MOTA BD241A 3 RCA D44C8 3 GESY	<b>NSP5980</b> TIP41B 1 MOTA BD243B 3 RCA BDX77 3 PHIN D44VM10 3 GESY STD5903 3 SOD	<b>OP304</b> SD2410-3 1 HON STPD1610-3 2 STE CLR3180 3 CLA GS1030-2 3 GSI GS1030-3 3 GSI OP305 3 TRWO	<b>OP500SLE</b> XC500E 1 NSC FPT131 2 FSC FPT132 2 FSC SDP8405-2 2 HON K5504 3 OTK K5505 3 OTK SFH309 3 SIEX XC500C 3 NSC XC500D 3 NSC	<b>OP609</b> LS600 1 TII SD2440-1 2 HON STPT60 2 STE GS1020-1 3 GSI OP601 3 TRWO OP640 3 TRW STPT61 3 STE TIL601 3 TII	<b>OP802</b> TIL602 1 TII 1N5723 2 TII BPX621 2 SIEG BPX621I 2 SIEG CLT3160 2 CLA MRD601 2 MOTA SD2440-2 2 HON STPT62 2 STE TIL602HR 2 TII
<b>NSP3055</b> MJE3055T 1 MOTA PH3055T 3 APX	<b>NSP5981</b> TIP41B 1 MOTA BD243B 3 RCA BDX77 3 PHIN D44VM10 3 GESY STD5903 3 SOD	<b>OP305</b> SD2410-3 1 HON CLR3180 3 CLA GS1030-2 3 GSI GS1030-3 3 GSI OP305 3 TRWO	<b>OP500SLE</b> XC500E 1 NSC FPT131 2 FSC FPT132 2 FSC SDP8405-2 2 HON K5504 3 OTK K5505 3 OTK SFH309 3 SIEX XC500C 3 NSC XC500D 3 NSC	<b>OP610</b> LS600 1 TII SD2440-1 2 HON STPT60 2 STE GS1020-1 3 GSI OP601 3 TRWO OP640 3 TRW STPT61 3 STE TIL601 3 TII	<b>OP803</b> TIL602 1 TII 1N5723 2 TII BPX621 2 SIEG BPX621I 2 SIEG CLT3160 2 CLA MRD601 2 MOTA SD2440-2 2 HON STPT62 2 STE TIL602HR 2 TII
<b>NSP4918</b> TIP30 1 MOTA BD138 3 PHIN BD240 3 RCA D45C4 3 GESY STD3575 3 SOD STD3578 3 SOD	<b>NSP5982</b> TIP41B 1 MOTA BD243B 3 RCA BDX77 3 PHIN D44VM10 3 GESY STD5903 3 SOD	<b>OP306</b> SD2410-3 1 HON CLR3180 3 CLA GS1030-2 3 GSI GS1030-3 3 GSI OP305 3 TRWO	<b>OP500SLE</b> XC500E 1 NSC FPT131 2 FSC FPT132 2 FSC SDP8405-2 2 HON K5504 3 OTK K5505 3 OTK SFH309 3 SIEX XC500C 3 NSC XC500D 3 NSC	<b>OP611</b> TIL601 1 TII 1N5722 2 TII SD2440-1 2 HON STPT61 2 STE TIL601HR 2 TII GS1020-1 3 GSI LISA5601 3 GESY MRD601 3 MOTA STPT60 3 STE	<b>OP804</b> TIL604 1 TII 1N5725 2 TII BPX621V 2 SIEG CLT3170 2 CLA MRD603 2 MOTA MRD604 2 MOTA SD2440-4 2 HON STPT64 2 STE TIL604HR 2 TII GS1020-4 3 GSI LISA5604 3 GESY OP644 3 TRW STPT1630-3 3 STE STPT1630-4 3 STE TIL603 3 TII TIL608 3 TII
<b>NSP4919</b> TIP30A 1 MOTA BD240A 3 RCA D45C10 3 GESY STD3577 3 SOD	<b>NSP5983</b> TIP41B 1 MOTA BD243B 3 RCA BDX77 3 PHIN D44VM10 3 GESY STD5903 3 SOD	<b>OP307</b> SD2410-3 1 HON CLR3180 3 CLA GS1030-2 3 GSI GS1030-3 3 GSI OP305 3 TRWO	<b>OP500SLE</b> XC500E 1 NSC FPT131 2 FSC FPT132 2 FSC SDP8405-2 2 HON K5504 3 OTK K5505 3 OTK SFH309 3 SIEX XC500C 3 NSC XC500D 3 NSC	<b>OP612</b> TIL601 1 TII 1N5722 2 TII SD2440-1 2 HON STPT61 2 STE TIL601HR 2 TII GS1020-1 3 GSI LISA5601 3 GESY MRD601 3 MOTA STPT60 3 STE	<b>OP805</b> TIL604 1 TII 1N5725 2 TII BPX621V 2 SIEG CLT3170 2 CLA MRD603 2 MOTA MRD604 2 MOTA SD2440-4 2 HON STPT64 2 STE TIL604HR 2 TII GS1020-4 3 GSI LISA5604 3 GESY OP644 3 TRW STPT1630-3 3 STE STPT1630-4 3 STE TIL603 3 TII TIL608 3 TII
<b>NSP4921</b> TIP29 1 MOTA BD239 3 RCA D44C4 3 GESY	<b>NSP5984</b> 2N6489 1 MOTA BDT82 3 APX DE332 3 DGE	<b>OP308</b> SD2410-3 1 HON CLR3180 3 CLA GS1030-2 3 GSI GS1030-3 3 GSI OP305 3 TRWO	<b>OP500SLE</b> XC500E 1 NSC FPT131 2 FSC FPT132 2 FSC SDP8405-2 2 HON K5504 3 OTK K5505 3 OTK SFH309 3 SIEX XC500C 3 NSC XC500D 3 NSC	<b>OP613</b> TIL602 1 TII 1N5723 2 TII BPX621 2 SIEG BPX621I 2 SIEG CLT3160 2 CLA MRD601 2 MOTA SD2440-2 2 HON STPT62 2 STE TIL602HR 2 TII	<b>OP806</b> TIL604 1 TII 1N5725 2 TII BPX621V 2 SIEG CLT3170 2 CLA MRD603 2 MOTA MRD604 2 MOTA SD2440-4 2 HON STPT64 2 STE TIL604HR 2 TII GS1020-4 3 GSI LISA5604 3 GESY OP644 3 TRW STPT1630-3 3 STE STPT1630-4 3 STE TIL603 3 TII TIL608 3 TII
<b>NSP4922</b> TIP29A 1 MOTA BD137 3 PHIN BD239A 3 RCA D44C7 3 GESY	<b>NSP5985</b> 2N6490 1 MOTA BDT82 3 APX	<b>OP309</b> SD2410-3 1 HON CLR3180 3 CLA GS1030-2 3 GSI GS1030-3 3 GSI OP305 3 TRWO	<b>OP500SLE</b> XC500E 1 NSC FPT131 2 FSC FPT132 2 FSC SDP8405-2 2 HON K5504 3 OTK K5505 3 OTK SFH309 3 SIEX XC500C 3 NSC XC500D 3 NSC	<b>OP614</b> TIL602 1 TII 1N5723 2 TII BPX621 2 SIEG BPX621I 2 SIEG CLT3160 2 CLA MRD601 2 MOTA SD2440-2 2 HON STPT62 2 STE TIL602HR 2 TII	<b>OP807</b> TIL604 1 TII 1N5725 2 TII BPX621V 2 SIEG CLT3170 2 CLA MRD603 2 MOTA MRD604 2 MOTA SD2440-4 2 HON STPT64 2 STE TIL604HR 2 TII GS1020-4 3 GSI LISA5604 3 GESY OP644 3 TRW STPT1630-3 3 STE STPT1630-4 3 STE TIL603 3 TII TIL608 3 TII